			to put all promises in writing. Keep this form.	
Infiniti	Q50	2020	JN1EV7AP0LM207614	
		YEAR	VEHICLE IDENTIFICATION NUMBER (VIN)	
WARRANTIES	FOR THIS VEHIC	LE:		
	2 - NO D	EALER	NARRANTY	
THE DEALE	R DOES NOT PROVIDE	A WARRANTY FOR AN	Y REPAIRS AFTER SALE.	
	LER WA	RRANT		
	RANTY			
		nav 100 % of the labor of	nd <u>100</u> % of the parts for the covered systems	
			of the warranty, and for any documents that	
•	anty coverage, exclusions may give you additional rig		obligations. Implied warranties under your	
SYSTEMS COVERED: ENGINE			DURATION:	
TRANSMISSION			<u>1,000 miles</u> 1,000 miles	
POWER STEERING			1,000 miles	
AIR CONDITIONING			1,000 miles	
	kes, tires, or alignments ARE NOT			
	VARRANTIES FO			
			rer's original warranty has not expired on some	
components of the			rel s'original warranty has not expired on some	
MANUFACTURE	R'S USED VEHICLE WAF	RRANTY APPLIES.		
	EHICLE WARRANTY APP	PLIES.		
Ask the dealer for a cooligations.	opy of the warranty docun	nent and an explanation o	of warranty coverage, exclusions, and repair	
coverage, deduct		. If you buy a service cor	le for an extra charge. Ask for details about ntract within 90 days of your purchase of this litional rights.	
			IICLE ON OR OFF THE LOT.	
ASK THE DEALER	IF TOUR MECHANIC C	AN INSPECT THE VEH	ICLE ON OR OFF THE LOT.	
-			<b>SAFETY RECALLS.</b> For information on sk for open safety recalls, visit safercar.gov.	
			make the best use of the resources on	
SEE OTHER SIDE f		information, including	g a list of major defects that may occur in	

Here is a list of some major defects that may occur in used vehicles.

#### Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

#### Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

#### Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

#### Cooling System

Leakage including radiator Improperly functioning water pump

#### Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

#### Fuel System

## Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

#### Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags** 

#### Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

#### Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning improperly

#### Tires

Tread depth less than 2/32 inch Sizes mismatched

#### Visible damage

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

#### Exhaust System

Leakage Catalytic Converter

## DEALER NAME

<u>Chacon Autos, Ltd.</u>

# 1400 SE. Military Dr, San Antonio, TX 78214

TELEPHONE

## chaconinfo@chaconautos.com

210-922-4000 FOR COMPLAINTS AFTER SALE, CONTACT:

# Contact service department at 210-922-4000

**IMPORTANT:** The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).