IMPORTANT: Spoken promises are difficult to enforce Hyundai Santa Fe	2018	5NMZT3LB2JH09261
VEHICLE MAKE MODEL	YEAR	VEHICLE IDENTIFICATION NUMBER (VIN
WARRANTIES FOR THIS VEHICLE:		
AS IS - NO DEA THE DEALER DOES NOT PROVIDE A WAR		
	RANTY	
	dealer for a copy o	
SYSTEMS COVERED:	DURATIO	N:
ENGINE	1,000 mile	es
TRANSMISSION	1,000 mile	es
POWER STEERING	1,000 mile	es
AIR CONDITIONING	1,000 mile	es
Wearable parts such as brakes, tires, or alignments ARE NOT Warranti	ied	
NON-DEALER WARRANTIES FOR TH	IS VEHICLE:	
MANUFACTURER'S WARRANTY STILL APPLIES components of the vehicle.	The manufactur	rer's original warranty has not expired on some
MANUFACTURER'S USED VEHICLE WARRANT	Y APPLIES.	
OTHER USED VEHICLE WARRANTY APPLIES.		
Ask the dealer for a copy of the warranty document an obligations.	d an explanation o	f warranty coverage, exclusions, and repair
SERVICE CONTRACT. A service contract on this coverage, deductible, price, and exclusions. If you vehicle, <i>implied warranties</i> under your state's laws	u buy a service cor	tract within 90 days of your purchase of this
ASK THE DEALER IF YOUR MECHANIC CAN IN	SPECT THE VEH	ICLE ON OR OFF THE LOT.
OBTAIN A VEHICLE HISTORY REPORT AND CHI how to obtain a vehicle history report, visit ftc.gov/us You will need the vehicle identification number (VIN these sites.	sedcars. To chec	k for open safety recalls, visit safercar.gov.
SEE OTHER SIDE for important additional inform	nation, including	g a list of major defects that may occur in

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

(DOT specs.)

Steering System

Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Too much free play at steering wheel

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

improperly

Wheels

Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME

<u>Chacon Autos, Ltd.</u>

3315 E Pioneer Pkwy, Arlington, TX 76010

TELEPHONE

chaconinfo@chaconautos.com

214-826-6000 FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 214-826-6000

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).