			put all promises in writing. Keep this form.
Mitsubishi	Outlander Sport		JA4APUAU2MU02414 ²
		YEAR	VEHICLE IDENTIFICATION NUMBER (VIN)
WARRANTIES FOR	THIS VEHICLE:		
A3 I3 -	NU DEA		VARRANTY
THE DEALER DOES		RANTY FOR ANY	REPAIRS AFTER SALE.
		RANTY	7
FULL WARRANTY.			
that fail during the wa	arranty period. Ask the de erage, exclusions, and th	ealer for a copy of	d <u>100</u> % of the parts for the covered systems the warranty, and for any documents that bligations. <i>Implied warranties</i> under your
SYSTEMS COVERED:		DURATION	:
ENGINE		1,000 miles	
TRANSMISSION		1,000 miles	
POWER STEERING		1,000 miles	
AIR CONDITIONING		1,000 miles	
Wearable parts such as brakes, tires, or	alignments ARE NOT Warrantie	d	
NON-DEALER WARR	ANTIES FOR THI	S VEHICLE:	
MANUFACTURER'S WAR components of the vehicle		. The manufacture	er's original warranty has not expired on some
MANUFACTURER'S USE	D VEHICLE WARRANTY	APPLIES.	
	WARRANTY APPLIES.		
Ask the dealer for a copy of the obligations.	e warranty document and	an explanation of	warranty coverage, exclusions, and repair
	e, and exclusions. If you	buy a service cont	for an extra charge. Ask for details about ract within 90 days of your purchase of this ional rights.
ASK THE DEALER IF YOUF	R MECHANIC CAN INS		CLE ON OR OFF THE LOT.
OBTAIN A VEHICLE HISTO how to obtain a vehicle histor	RY REPORT AND CHE	CK FOR OPEN S edcars. To check	SAFETY RECALLS. For information on for open safety recalls, visit safercar.gov. make the best use of the resources on
these sites.			
these sites.	rtant additional inform	ation. including	a list of major defects that may occur in

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

(DOT specs.)

Steering System

Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Too much free play at steering wheel

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

improperly

Wheels

Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME

<u>Chacon Autos, Ltd.</u>

3315 E Pioneer Pkwy, Arlington, TX 76010

TELEPHONE

chaconinfo@chaconautos.com

214-826-6000 FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 214-826-6000

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).