IMPORTANT: Spok Kia	en promises are difficult to Soul	enforce. Ask the dealer 2021	to put all promises in writing. Keep this form.	
	MODEL		KNDJ23AU3M7781837 VEHICLE IDENTIFICATION NUMBER (VIN)	
	FOR THIS VEHIC			
	IS - NO D	EALER	WARRANTY	
			Y REPAIRS AFTER SALE.	
	ALER WA	RRANT	ſ	
□ FULL WAR	RANTY.			
_		pay 100 % of the labor a	and 100 % of the parts for the covered systems	
that fail dur	ing the warranty period. As	sk the dealer for a copy	of the warranty, and for any documents that	
	ranty coverage, exclusions may give you additional rig		obligations. Implied warranties under your	
SYSTEMS COVER		DURATIO	N:	
ENGINE			1,000 miles	
TRANSMISSION			1,000 miles	
POWER STEERING		1,000 miles		
AIR CONDITIONING		1,000 miles		
Wearable parts such as bra	akes, tires, or alignments ARE NOT	Warrantied		
NON-DEALER	WARRANTIES FO	R THIS VEHICLE	:	
MANUFACTURE		PPLIES. The manufactu	irer's original warranty has not expired on some	
	ER'S USED VEHICLE WAF	RRANTY APPLIES.		
OTHER USED V	EHICLE WARRANTY APP	LIES.		
Ask the dealer for a obligations.	copy of the warranty docum	nent and an explanation	of warranty coverage, exclusions, and repair	
coverage, deduc		. If you buy a service co	ole for an extra charge. Ask for details about ntract within 90 days of your purchase of this ditional rights.	
			HICLE ON OR OFF THE LOT.	
-		-		
how to obtain a veh	icle history report, visit fto	.gov/usedcars. To che	SAFETY RECALLS. For information on ck for open safety recalls, visit safercar.gov. o make the best use of the resources on	
SEE OTHER SIDE used motor vehicle		information, includin	g a list of major defects that may occur in	

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME

<u>Chacon Autos, Ltd.</u>

1400 SE. Military Dr, San Antonio, TX 78214

TELEPHONE

chaconinfo@chaconautos.com

210-922-4000 FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 210-922-4000

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).