	Charger	2023	2C3CDXBG7PH52951
	ODEL	YEAR	VEHICLE IDENTIFICATION NUMBER (VIN
WARRANTIES FOR TH	IS VEHICLE	:	
			WARRANTY
	DT PROVIDE A V	VARRANTY FOR AN'	Y REPAIRS AFTER SALE.
	R WAF	RANT	1
FULL WARRANTY.			
that fail during the warra	nty period. Ask t ge, exclusions, a	he dealer for a copy on the dealer's repair	and <u>100</u> % of the parts for the covered systems of the warranty, and for any documents that obligations. <i>Implied warranties</i> under your
SYSTEMS COVERED:		DURATIO	N:
ENGINE		<u>1,000 mil</u>	es
TRANSMISSION		<u>1,000 mil</u>	es
POWER STEERING		1,000 mil	es
AIR CONDITIONING		1,000 mil	es
Wearable parts such as brakes, tires, or alig	nments ARE NOT Wa	rrantied	
NON-DEALER WARRAM	ITIES FOR	THIS VEHICLE	:
MANUFACTURER'S WARRA components of the vehicle.	NTY STILL APPI	LIES. The manufactu	rer's original warranty has not expired on some
MANUFACTURER'S USED V	EHICLE WARRA	ANTY APPLIES.	
OTHER USED VEHICLE WA	RRANTY APPLIE	ES.	
Ask the dealer for a copy of the w obligations.	arranty documen	t and an explanation o	of warranty coverage, exclusions, and repair
	nd exclusions. If	you buy a service cor	le for an extra charge. Ask for details about ntract within 90 days of your purchase of this ditional rights.
ASK THE DEALER IF YOUR M	ECHANIC CAN	INSPECT THE VEH	ICLE ON OR OFF THE LOT.
how to obtain a vehicle history r	eport, visit ftc.go	v/usedcars. To chec	SAFETY RECALLS. For information on ck for open safety recalls, visit safercar.gov. o make the best use of the resources on
SEE OTHER SIDE for importa	nt additional in	formation, including	g a list of major defects that may occur in

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through

Dog tracks—bent or twisted frame Engine

Oil leakage, excluding normal seepage Cracked block or head Belts missing or inoperable Knocks or misses related to camshaft lifters and push rods Abnormal exhaust discharge

Transmission & Drive Shaft

- Improper fluid level or leakage, excluding normal seepage
- Cracked or damaged case which is visible Abnormal noise or vibration caused by faulty transmission or drive shaft
- Improper shifting or functioning in any gear Manual clutch slips or chatters

Differential

- Improper fluid level or leakeage, excluding normal seepage
- Cracked of damaged housing which is visible
- Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator Improperly functioning water pump

Electrical System

Battery leakage Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories Gauges or warning devices Air conditioner Heater & Defroster

Brake System

Failure warning light broken Pedal not firm under pressure (DOT spec.) Not enough pedal reserve (DOT spec.) Does not stop vehicle in straight line (DOT spec.) Hoses damaged Drum or rotor too thin (Mfgr. Specs) Lining or pad thickness less than 1/32 inch Power unit not operating or leaking Structural or mechanical parts damaged **Air Bags**

Steering System

Too much free play at steering wheel (DOT specs.) Free play in linkage more than 1/4 inch Steering gear binds or jams Front wheels aligned improperly (DOT specs.) Power unit belts cracked or slipping Power unit fluid level improper

Suspension System

Ball joint seals damaged Structural parts bent or damaged Stabilizer bar disconnected Spring broken Shock absorber mounting loose Rubber bushings damaged or missing Radius rod damaged or missing Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch Sizes mismatched

Visible damage

- Wheels
- Visible cracks, damage or repairs Mounting bolts loose or missing

Exhaust System

Leakage Catalytic Converter

DEALER NAME

<u>Chacon Autos, Ltd.</u>

1400 SE. Military Dr, San Antonio, TX 78214

TELEPHONE

chaconinfo@chaconautos.com

210-922-4000 FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 210-922-4000

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).