

BUYERS GUIDE

IMPORTANT: Spoken promises are difficult to enforce. Ask the dealer to put all promises in writing. Keep this form.

Nissan

VEHICLE MAKE

Versa

MODEL

2024

YEAR

3N1CN8DV2RL903921

VEHICLE IDENTIFICATION NUMBER (VIN)

WARRANTIES FOR THIS VEHICLE:



AS IS - NO DEALER WARRANTY

THE DEALER DOES NOT PROVIDE A WARRANTY FOR ANY REPAIRS AFTER SALE.



DEALER WARRANTY



FULL WARRANTY.



LIMITED WARRANTY. The dealer will pay 100 % of the labor and 100 % of the parts for the covered systems that fail during the warranty period. Ask the dealer for a copy of the warranty, and for any documents that explain warranty coverage, exclusions, and the dealer's repair obligations. *Implied warranties* under your state's laws may give you additional rights.

SYSTEMS COVERED:

ENGINE

TRANSMISSION

POWER STEERING

AIR CONDITIONING

Wearable parts such as brakes, tires, or alignments ARE NOT Warrantied

DURATION:

1,000 miles

1,000 miles

1,000 miles

1,000 miles

NON-DEALER WARRANTIES FOR THIS VEHICLE:

☐ MANUFACTURER'S WARRANTY STILL APPLIES. The manufacturer's original warranty has not expired on some components of the vehicle.

☐ MANUFACTURER'S USED VEHICLE WARRANTY APPLIES.

☐ OTHER USED VEHICLE WARRANTY APPLIES.

Ask the dealer for a copy of the warranty document and an explanation of warranty coverage, exclusions, and repair obligations.

☐ SERVICE CONTRACT. A service contract on this vehicle is available for an extra charge. Ask for details about coverage, deductible, price, and exclusions. If you buy a service contract within 90 days of your purchase of this vehicle, *implied warranties* under your state's laws may give you additional rights.

ASK THE DEALER IF YOUR MECHANIC CAN INSPECT THE VEHICLE ON OR OFF THE LOT.

OBTAIN A VEHICLE HISTORY REPORT AND CHECK FOR OPEN SAFETY RECALLS. For information on how to obtain a vehicle history report, visit ftc.gov/usedcars. To check for open safety recalls, visit safercar.gov. You will need the vehicle identification number (VIN) shown above to make the best use of the resources on these sites.

SEE OTHER SIDE for important additional information, including a list of major defects that may occur in used motor vehicles.

Si el concesionario gestiona la venta en español, pídale una copia de la Guía del Comprador en español.

Here is a list of some major defects that may occur in used vehicles.

Frame & Body

Frame-cracks, corrective welds, or rusted through
Dog tracks—bent or twisted frame

Engine

Oil leakage, excluding normal seepage
Cracked block or head
Belts missing or inoperable
Knocks or misses related to camshaft lifters and push rods
Abnormal exhaust discharge

Transmission & Drive Shaft

Improper fluid level or leakage, excluding normal seepage
Cracked or damaged case which is visible
Abnormal noise or vibration caused by faulty transmission or drive shaft
Improper shifting or functioning in any gear
Manual clutch slips or chatters

Differential

Improper fluid level or leakage, excluding normal seepage
Cracked or damaged housing which is visible
Abnormal noise or vibration caused by faulty differential

Cooling System

Leakage including radiator
Improperly functioning water pump

Electrical System

Battery leakage
Improperly functioning alternator, generator, battery, or starter

Fuel System

Visible leakage

Inoperable Accessories

Gauges or warning devices
Air conditioner
Heater & Defroster

Brake System

Failure warning light broken
Pedal not firm under pressure (DOT spec.)
Not enough pedal reserve (DOT spec.)
Does not stop vehicle in straight line (DOT spec.)
Hoses damaged
Drum or rotor too thin (Mfr. Specs)
Lining or pad thickness less than 1/32 inch
Power unit not operating or leaking
Structural or mechanical parts damaged

Air Bags

Steering System

Too much free play at steering wheel (DOT specs.)
Free play in linkage more than 1/4 inch
Steering gear binds or jams
Front wheels aligned improperly (DOT specs.)
Power unit belts cracked or slipping
Power unit fluid level improper

Suspension System

Ball joint seals damaged
Structural parts bent or damaged
Stabilizer bar disconnected
Spring broken
Shock absorber mounting loose
Rubber bushings damaged or missing
Radius rod damaged or missing
Shock absorber leaking or functioning improperly

Tires

Tread depth less than 2/32 inch
Sizes mismatched
Visible damage

Wheels

Visible cracks, damage or repairs
Mounting bolts loose or missing

Exhaust System

Leakage
Catalytic Converter

DEALER NAME

Chacon Autos, Ltd.

ADDRESS

1400 SE. Military Dr, San Antonio, TX 78214

TELEPHONE

210-922-4000

EMAIL

chaconinfo@chaconautos.com

FOR COMPLAINTS AFTER SALE, CONTACT:

Contact service department at 210-922-4000

IMPORTANT: The information on this form is part of any contract to buy this vehicle. Removing this label before consumer purchase (except for purpose of test-driving) violates federal law (16 C.F.R. 455).